

09500592.021000




FIGURE 1




FIGURE 2




FIGURE 3

00000000 26500560




FIGURE 4




FIGURE 5

09500592 021000




FIGURE 6a




FIGURE 6b

000720" 26500560

COARSE STATIC ATTITUDE ADJUST  
EFFECT OF BOTTOM SPING ARM SCAN ON PITCH




FIGURE 7

FINE STATIC ATTITUDE ADJUST  
EFFECT OF BOTTOM SPING ARM SCAN ON PITCH




FIGURE 8



000120" 26500560

COARSE STATIC ATTITUDE ADJUST  
EFFECT OF TOP SPRING ARM SCAN ON PITCH




FIGURE 9

FINE STATIC ATTITUDE ADJUST  
EFFECT OF TOP SPRING ARM SCAN ON PITCH




FIGURE 10

050302-021000



000720" 28500560




FIGURE 13




FIGURE 14

COARSE STATIC ATTITUDE ADJUST  
EFFECT OF TOP RIGHT SPRING ARM SCAN ON ROLL




FIGURE 15

FINE STATIC ATTITUDE ADJUST  
EFFECT OF TOP RIGHT SPRING ARM SCAN ON ROLL




FIGURE 16

000720" 26500560




FIGURE 17







FIGURE 18







100